

Pt CMP:

Abrasive	Chem	pH	Pt (A/min)
----------	------	----	------------

lower pH to 1 or 2

Use TMAH to titrate p2A to pH 7 or even pH 12.